


# ELECTRONIC EDGE FINDER

MADE IN U.S.A.




Inspect edge finder before use by making contact between ball and body using paper clip or metal coin.

1. **Do not** place Edge Finder's body below work surface. Be sure that ball center is approximately  $1/32"$  or 1 mm. below work surface.
2. **Feed carefully** toward work piece. When a contact is made between ball and work piece, the LED lamp will illuminate.
3. This Edge Finder is damage-free with spring-sustained ball. **In case of over-travel**, move backward and feed carefully. On touch the LED lamp will illuminate.

At this position, half diameter of ball reads exact location.

T.I.R within  $.0004"$  - 0.01 mm.



1	BATTERY #A76	TT-3509
2	LAMP #338	TT-3510
3	SPRING	TT-2510
4	BALL	TT-2504